

Product Safety Recall



YAMAHA MT10 2016 ~ 2020, MT09 2018 ~ 2020

NIKEN 2018 ~ 2020, XT1200 2014 ~ 2020

Brake Switch Exchange

MODEL	MODEL YEAR	FRAME NUMBER PREFIX No.	FROM	TO
MT10	2016	RN454	000003	000440
MT10	2017 - 2020	RN45B	000001	000503
MT10SP	2017 - 2020	RN457	000003	000465
MT09TRASP	2018 - 2020	RN576	000001	000398
NIKEN	2018	RN582	000001	000073
NIKEN	2019 - 2020	RN585	000301	000335
XT1200Z	2014 - 2016	DP044	000001	000096
XT1200ZE	2014 - 2016	DP048	000003	000211
XT1200ZE	2017 - 2020	DP077	000001	000087

WHAT ARE THE DEFECTS?

The faulty brake switch can inhibit the cruise control and constantly illuminate the rear brake light.

WHAT ARE THE HAZARDS?

If brake lights constantly illuminate, this may give other road users incorrect vehicle signals, increasing the risk of an accident or injury or death to rider(s) and/or other road users.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the brake switch replaced.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at <http://www.yamaha-motor.co.nz/> or call 09 265 6500.

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See www.recalls.govt.nz/product-safety-alerts for
other New Zealand consumer product recalls