

# Product Safety Recall

VX1050A-W	VX1050E-W	VX1800A-W
		
VX1800C-W	GP1800A-W	GP1800B-W
		

Model name	Model code	Model year	Affected Primary ID Range
VX1050-W	F4N	2021	F4N-0800101 ~ 0803740 0804533 ~ 0806349
VX1800-W	F4S	2021	F4S-0800101 ~ 0803461
GP1800A-W	F4P	2021	F4P-0800101 ~ 0801740 0802510 ~ 0802620
GP1800B-W	F4M	2021	F4M-0800101 ~ 0801340

## Yamaha WaveRunner MY2021

**Sold by Authorised Yamaha Dealers between 30 November 2020  
and 31 December 2021**

**Defect:** A poorly install sensor in the shut-off switch assembly may allow water to seep inside the sensor (switch housing) and become corroded, causing an intermittent connection.

**Hazard:** An intermittent connection may result in a malfunction with the engine shut-off switch. If the switch malfunctions, the engine may not stop when the lanyard is pulled. This could result in loss of control of the watercraft and an accident causing injury or death.

**What to do:** When parts become available from June 2021, consumers will be advised to contact their local Yamaha WaveRunner dealership to organise for inspection and repair.

**Contact details:** Consumers can find their nearest authorised Yamaha dealership by visiting <https://www.yamaha-motor.co.nz/> For further information, contact Yamaha by phone on 0800 926 242 or email: [cr@yamaha-motor.com.au](mailto:cr@yamaha-motor.com.au)

**Yamaha Motor New Zealand Ltd.**  
58 Lady Ruby Drive  
East Tamaki  
Auckland

See [www.recalls.govt.nz](http://www.recalls.govt.nz) for  
other New Zealand consumer product recalls

Issued: 12/2021