

Product Safety Recall

YAMAHA Water Vehicle

FB1800/FC1800/FX1800/GP1800/VX1050/VX1800

Model name	Model code	Model year	Affected PID range
FB1800	F3V	2021 - 2022	F3V-0809781 ~ F3V-0814939
			F3V-0814941 ~ F3V-0816580
FC1800	F3X	2021	F3X-0813421 ~ F3X-0822500
FX1800	F5G	2022	F5G-0800101 ~ F5G-0801620
GP1800A	F4P	2021 - 2022	F4P-0800101 ~ F4G-0805780
GP1800B	F4M	2021 - 2022	F4M-0800101 ~ F4M-0802900
VX1050	F4N	2021 - 2022	F4N-0800101 ~ F4N-0810860
VX1800	F4S	2021 - 2022	F4S-0800101 ~ F4S-0806620

Sold by authorised Yamaha dealers between July 2020 to February 2022

Defect

The fuel filler neck can be pushed into the hull if the refuelling nozzle is inserted with too much force. This may prevent sealing between the filler cap and filler neck and allow fuel to leak.

Hazard

A fuel leak increases the risk of fire, which could result in severe injury or death as well as damage to property.

What to do

Consumers are requested to contact your local Yamaha Dealer to set up an appointment to have this repair carried out to free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.co.nz/>

For more information, contact Yamaha Motor New Zealand on 09 265 6500.

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See www.recalls.govt.nz/product-safety-alerts for
other New Zealand consumer product recalls