


Product Safety Recall



YAMAHA SR400 Motorcycle Oil Hose Leak

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
SR400	2014-2017	RH052	000001	000402

WHAT ARE THE DEFECTS?

Incorrect tightening torque applied to the engine oil HOSE 2 flare nut.

WHAT ARE THE HAZARDS?

May result in engine oil leakage from the engine oil Hose 2 fitting onto the engine assembly.

WHAT IS THE REMEDY?

Yamaha dealers will inspect the Hose 2 fitting, re-tighten or replace as necessary.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for
other New Zealand consumer product recalls