

Product Safety Recall



YAMAHA AG125 Motorcycle Fuel Cock

MODEL	MODEL CODE	PREFIX No.	FRAME NUMBER	
			Start	End
AG125	BF85	CE28W	0013630	0014567

WHAT ARE THE DEFECTS?

An incorrect press fitting procedure during assembly may have damaged the fuel cock tube, which may lead to fuel leakage.

WHAT ARE THE HAZARDS?

If fuel leaks in the presence of an ignition source this may cause a fire, increasing the risk of serious injury or death to riders.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the fuel cock assembly replaced.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

If you need help finding a Yamaha Dealer in your area, simply visit us on the web at www.yamaha-motor.co.nz/ownership/support or call 09 265 6500

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See www.recalls.govt.nz/product-safety-alerts for
other New Zealand consumer product recalls