

Product Safety Recall

YAMAHA MT09/XSR900 Motorcycle Handlebar Exchange

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
MT09	2014 - 2015	RN294	000003	001791
MT09A	2015	RN29L	000001	000767
	2016	RN29V	000001	000451
	2017	RN437	000002	000414
MT09TRA	2015 - 2016	RN29K	000004	001173
	2017	RN43B	000001	000110
XSR900	2016 - 2017	RN434	000003	000609

WHAT ARE THE DEFECTS?

The lower handlebar holder may have been manufactured with improper paint application. Additionally, thread locking agent may not have been adequately applied to the stud bolt thread in the lower handlebar holder. Strong external impact may abrade the paint film causing axial force on the stud bolt.

WHAT ARE THE HAZARDS?

With engine vibration, the stud may loosen and fall off resulting in loss of control.

WHAT IS THE REMEDY?


Replacement of the handlebar clamp assembly.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your MT09/XSR remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>



Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for
other New Zealand consumer product recalls