


Product Safety Recall



YAMAHA TriCity (MW125) Scooter Primary Sheave Nut

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
MW125	2015	SE785	0049801	0050130
MW125A		SE78B	0086101	0086250

WHAT ARE THE DEFECTS?

The primary fixed sheave nut may loosen during riding due to inadequate axial tightening torque. If the nut loosens off, the primary sheave may dislodge and contact the crank case cover.

WHAT ARE THE HAZARDS?

The primary sheave may become jammed by the crank case cover resulting in engine stalling during operation and the inability to restart the engine. This condition could cause loss of control of the scooter resulting in an accident and injury to rider or other road users,

WHAT TO DO?

The owner must contact the nearest Yamaha dealer to have the defective parts replaced with new counter measure parts free of charge as soon as possible.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
Auckland, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for
other New Zealand consumer product recalls