

# Product Safety Recall



## YAMAHA YZF-R3/MT03 Motorcycle Radiator Coolant Hose Leak

MODEL	FRAME NUMBER		
	Prefix	To	From
MT03LA 2018	RH072	001001	008240
YZF-R3A 2015 ~ 2016	RH124	001001	001280
YZF-R3A 2018	RH07L	001001	005800
MT03LA 2016 ~ 2018	RH127	001001	001120

### WHAT IS THE DEFECT?

Due to insufficient hose material curing at manufacturing, cracking may develop in the radiator coolant hose.

### WHAT ARE THE HAZARDS?

This may result in coolant leakage onto the road surface if cracks develop in the aging hose.

### WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the defective Hose/hoses replaced with the countermeasure hose.

### WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

**Australian Importer/Distributor**  
**Yamaha Motor New Zealand**  
58 Lady Ruby Drive, East Tamaki  
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for  
other New Zealand consumer product recalls