


Product Safety Recall



YAMAHA YZF-R3/MT03 Motorcycle Torsion Spring Breakage

MODEL		FRAME NUMBER	
	PREFIX	FROM	TO
YZF-R3A 2015 ~ 2016			
MT03LA 2016	RH072	001001	004400
	RH07L	001001	001760

WHAT IS THE DEFECT?

Due to a broken shift mechanism torsion spring, riders may not be able to select the desired gear.

WHAT ARE THE HAZARDS?

Inability to shift gears properly resulting in difficulty in manoeuvring the vehicle while riding.

WHAT IS THE REMEDY?

To correct this defect, Yamaha is initiating a Factory Modification Campaign, whereby affected models must have the shift mechanism torsion spring exchanged with a new counter measure one.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for
other New Zealand consumer product recalls