

Product Safety Recall



Do you own this product? Yamaha Golf Car G29 2/4-Seater or UMX (Utility)



Utility (2016-2022)



Why the product is recalled: The accelerator pedal return spring may break during use and the accelerator pedal may not return when released.

Hazard: Risk of serious injury from collision if the accelerator pedal doesn't return when released and the vehicle doesn't slow down as expected. At least 1 incident has occurred because of this defect.



Stop using these vehicles and check if the golf car is affected. Contact your local Yamaha dealer to arrange for a free repair.

Send us an email if you are unable to return the product due to it being sold or gifted it to another person cr@yamaha-motor.com.au



If you need help finding a Yamaha Dealer in your area, simply visit us on the web http://www.yamaha-motor.co.nz/ or CALL 09 265 6500



Purchased from: Authorised Yamaha Dealers

New Zealand Importer/Distributor Yamaha Motor New Zealand 58 Lady Ruby Drive, East Tamak

See http://www.recalls.govt.nz/ for other New Zealand consumer product recalls