

Product Safety Recall



YAMAHA MY22 XTZ690 Tenere Caliper Bolt

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX No.	FROM	TO
XTZ690	2022	DM131	001024	001049

Sold by authorised Yamaha dealers between 12 October 2022 – 28 April 2023

Defect

The front caliper mounting bolts may not meet manufacturing specifications and could loosen. This could result in a reduction or loss in braking performance.

Hazard

A reduction or loss in braking performance could increase the risk of an accident causing injury or death to the rider, passenger and other road users.

What to do

Owners of affected vehicles can contact their authorised Yamaha Dealer to schedule an appointment to have the bolts inspected and if required, replaced free of charge.

Contact details

Consumers can find their nearest authorised Yamaha dealer by visiting <https://www.yamaha-motor.co.nz/>

If you no longer own this Motorcycle, please advise Yamaha Motor New Zealand on 09 265 6500 or email cr@yamaha-motor.com.au

New Zealand Importer/Distributor

Yamaha Motor New Zealand

58 Lady Ruby Drive, East Tamaki

NSW, New Zealand

See www.recalls.govt.nz/product-safety-alerts for
other New Zealand consumer product recalls