

Product Safety Recall



YAMAHA YZF-R3A Motorcycle Brake Hose Support Bracket

MODEL	MODEL YEAR	FRAME NUMBER		
		PREFIX	FROM	TO
YZF-R3A	2019	RH12H	001001	001240

WHAT ARE THE DEFECTS?

Front brake hose supporting bracket may dislodge.

WHAT ARE THE HAZARDS?

Continual rubbing between the brake hose and front fork can cause wearing of the brake hose and potentially lead to brake fluid loss. If the brake system was to lose fluid, this would decrease the effectiveness of the brakes and increase the chance of a crash causing serious injury to the rider and other road users.

WHAT IS THE REMEDY?

To correct these defects, Yamaha is initiating a Factory Modification Campaign, whereby affected YZF-R3A models must have a replacement brake hose bracket fitted.

WHAT TO DO?

You should contact your local Yamaha Dealer to set up an appointment to have your model remedied free of charge.

Contact details: for help finding your nearest authorised dealer call

09 265 6500 or visit the website: <https://www.yamaha-motor.co.nz/>

Australian Importer/Distributor
Yamaha Motor New Zealand
58 Lady Ruby Drive, East Tamaki
NSW, New Zealand

See <https://www.recalls.govt.nz/product-safety-alerts> for
other New Zealand consumer product recalls